

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Plumas County

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 North Fork Feather River	Left	1.89	04/22/2020 04/22/2020	Sterling York

LM Start		Rating **	A	Issue No.	1
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Operations & Maintenance Manuals			°	°
DWR ID	DWR_NA0015_01_s_2013_1				
Comment Code					
Inspector Comment					
The LMA has O&M manuals in their office.					

No Photos

LM Start		Rating **	A	Issue No.	2
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Emergency Supplies & Equipment			°	°
DWR ID	DWR_NA0015_01_s_2013_2				
Comment Code					
Inspector Comment					
The LMA has flood fight supplies and equipment at their yard.					

No Photos

LM Start		Rating **	A	Issue No.	3
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Flood Preparedness & Training			°	°
DWR ID	DWR_NA0015_01_s_2013_3				
Comment Code					
Inspector Comment					
The LMA has completed flood flight training, Winter 2019.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

Plumas County

View looking downstream waterside at the well maintained annual vegetation, Spring 2020.

View looking downstream landside at the well maintained annual vegetation, Spring 2020.

View of vehicle tracks accessing the levee on the waterside slope.

Page 2 of 3

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Plumas County

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 North Fork Feather River	Left	1.89	04/22/2020 04/22/2020	Sterling York

LM Start	0.82	Rating **	M	Issue No.	7
LM End	0.82	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			40.283462 °	40.283462 °
				-121.251156 °	-121.251156 °
DWR ID	DWR_NA0015_01_s_2020_7				
Comment Code					
T2 : Thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					
Trees with less than 4" diameter at chest height should be removed, Spring 2020.					

Photo 1 of 1 : SP_2020_NA0015_337_7_20200429_00007.jpg



View looking downstream landside at small pine trees on the levee slope, Spring 2020.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Plumas County

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 North Fork Feather River	Right	1.36	04/22/2020 04/22/2020	Sterling York

LM Start	0.01	Rating **	A	Issue No.	2
LM End	1.33	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			40.286428 °	40.272110 °
				-121.259994 °	-121.247060 °
DWR ID	DWR_NA0015_02_s_2020_2				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
The annual vegetation is well maintained, Spring 2020.					

Photo 1 of 1 : SP_2020_NA0015_338_2_20200429_00009.jpg



View looking upstream landside at the well maintained annual vegetation, Spring 2020.

LM Start	0.01	Rating **	A	Issue No.	3
LM End	1.33	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			40.286423 °	40.272110 °
				-121.259992 °	-121.247060 °
DWR ID	DWR_NA0015_02_s_2020_3				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
The annual vegetation is well maintained, Spring 2020.					

Photo 1 of 1 : SP_2020_NA0015_338_3_20200429_00008.jpg



View looking downstream waterside at the well maintained annual vegetation, Spring 2020.

*** Location**
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Plumas County

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 North Fork Feather River	Right	1.36	04/22/2020 04/22/2020	Sterling York

LM Start	0.55	Rating **	A/W	Issue No.	4
LM End	0.55	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			40.281950 °	40.281950 °
				-121.253710 °	-121.253710 °
DWR ID	DWR_NA0015_02_s_2012_4				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					
There is no sign of slope instability but should be monitored for the next year. The access has been blocked.					

Photo 1 of 1 : SP_2020_NA0015_338_4_20200227_00001.jpg



View of the undesignated vehicle access along the landside slope, there is no sign of slope instability but should be monitored.

LM Start	0.55	Rating **	A/W	Issue No.	5
LM End	0.55	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			40.281950 °	40.281950 °
				-121.253710 °	-121.253710 °
DWR ID	DWR_NA0015_02_s_2012_5				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					
There is no sign of slope instability but should be monitored for the next year. The access has been blocked.					

Photo 1 of 1 : SP_2020_NA0015_338_5_20200227_00002.jpg



View of the undesignated vehicle access along the waterside slope, there is no sign of slope instability but should be monitored.

*** Location**
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**
A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Plumas County

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 North Fork Feather River	Right	1.36	04/22/2020 04/22/2020	Sterling York

LM Start	0.56	Rating **	M	Issue No.	6
LM End	0.56	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			40.281897 °	40.281897 °
				-121.253372 °	-121.253372 °
DWR ID	DWR_NA0015_02_s_2020_6				
Comment Code					
T2 : Thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					
Trees with less than 4" diameter at chest height should be removed, Spring 2020.					

Photo 1 of 1 : SP_2020_NA0015_338_6_20200429_00010.jpg



View looking upstream landside at small pine trees on the levee slope, Spring 2020.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---